


TOPDON

TopScan Moto Quick User Guide



Thank you for purchasing the TOPDON TopScan Moto. This quick user guide will walk you through the basic setup and operation of the TopScan Moto wireless diagnostic tool. For the best user experience, carefully read and follow all the instructions and warnings.

1

Download & Install the APP



For iOS: Search for "**TopGuru**" in the **App Store** to download and install.
For Android: Search for "**TopScan**" in **Google Play** to download and install.

2

Register & Log In

Sign in to the topdon Account

Email

Password

☒ Remember Me [Forgot Password?](#)


[Don't have an account? Create Account](#)

Log In

Open the app and log in to your TOPDON account. (If you do not have an account, please register with your email.)

3

Bind the VCI




Tap **Me** > **Device Management** > **Add VCI**.

To get the serial number and activation code, please scan the QR code on the product. (Alternatively, once the Bluetooth connection between the TopScan Moto and your phone is established, the serial number and activation code will be automatically recognized.) Then, tap **Activate**.

4

Download the Diagnostic Software




You will need to download the motorcycle-specific software the first time you use the diagnostic function. Tap Diagnostics on the home screen and download the software you need.

TEL	+86-755-21612590 +1-833-629-4832 (North America) +34 930 038 094 (Europe)
EMAIL	SUPPORT@TOPDON.COM
WEBSITE	WWW.TOPDON.COM
FACEBOOK	@TOPDONOFFICIAL
X	@TOPDONOFFICIAL



5

Plug the TopScan Moto into the DLC of your motorcycle.




The Data Link Connector (DLC) of a motorcycle is typically located under the seat or near the engine (see the figure above).

Note: If the DLC of your motorcycle is not an OBD-II port, an adapter is required (not included) to connect the TopScan Moto to your motorcycle.

6


Turn the ignition and engine stop switch to the "ON" position.



The red LED light on the TopScan Moto indicates it is powered on.

7

Bluetooth Connection



Tap **Diagnostics** on the home screen, then tap **VCI** at the top right of the screen to establish a Bluetooth connection with the unit. When connection is established, the LED light on the unit will turn solid blue.

Your TopScan Moto is now ready for use.

FAQ

Q: What should I do if a communication error occurs?

A: Follow the steps below to identify the problem:

- 1) Check if the ignition is ON.
- 2) Check if the TopScan Moto is securely plugged into the motorcycle's DLC.
- 3) Turn the ignition off. Then, turn it on after 10 seconds and continue the operation.
- 4) Check if the motorcycle's control module is defective.

Q: Why do I need to download the diagnostic software after installing the app?

A: Since there are various motorcycle manufacturers, different diagnostic software is required for different brands.

Q: Do I need to update the firmware before using it for the first time?

A: Yes. Firmware will automatically update to the latest version once the TopScan Moto is connected with your phone via Bluetooth. You can also tap **Me > Firmware Update** to update the firmware manually.

Compliance Information

Regulatory Compliance

FCC ID: 2AVVW-TOPSCAN
IC: 32511-TOPSCAN
HVIN: TopScan Moto

FCC &ISED Statement

This device complies with Part 15 of the FCC Rules [and contains license-exempt transmitter(s)/receiver(s) that comply with Innovation, Science and Economic Development Canada's licence-exempt RSS standard(s)].

Operation is subject to the following two conditions:

(1) This device may not cause harmful interference, and (2) This device must accept any interference received, including interference that may cause undesired operation of the device.

L'émetteur/récepteur exempt de licence contenu dans le présent appareil est conforme aux CNR d'Innovation, Sciences et Développement économique Canada applicables aux appareils radio exempts de licence.

L'exploitation est autorisée aux deux conditions suivantes:

(1) l'appareil ne doit pas produire de brouillage, et

(2) l'appareil doit accepter tout brouillage radioélectrique subi, même si le brouillage est susceptible d'en compromettre le fonctionnement.

Changes or modifications not expressly approved by the party responsible for compliance could void your authority to operate the equipment.

This equipment complies with FCC and ISED radiation exposure limits set forth for an uncontrolled environment without restriction.

Cet équipement respecte les limites d'exposition aux rayonnements FCC et ISED fixées pour un environnement non contrôlé sans restriction.

FCC VOC

This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can

radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

-- Reorient or relocate the receiving antenna.

-- Increase the separation between the equipment and receiver.

-- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.

-- Consult the dealer or an experienced radio/TV technician for help.

In case this equipment has to be subject to FCC/IC SAR (Specific Absorption Rate) exposure test, this equipment is designed to meet the requirements for exposure to radio waves established by the FCC and ISED. These requirements set a SAR limit of 1.6 W/kg averaged over one gram of tissue. The highest SAR value reported under this standard during product certification for use when properly worn on the body or on the head, with no separation.

FCC Caution:

The device for operation in the band 5150-5250 MHz is only for indoor use to reduce the potential for harmful interference to co-channel mobile satellite systems;

IC Caution:

1. The device for operation in the band 5150-5250 MHz is only for indoor use to reduce the potential for harmful interference to co-channel mobile satellite systems;

2. for devices with detachable antenna(s), the maximum antenna gain permitted for devices in the band 5725-5850 MHz shall be such that the equipment still complies with the e.i.r.p. limits specified for point-to-point and non-point-to-point operation as appropriate.

1. les dispositifs fonctionnant dans la bande 5150-5250 MHz sont réservés uniquement pour une utilisation à l'intérieur afin de réduire les risques de brouillage préjudiciable aux systèmes de satellites mobiles utilisant les mêmes canaux;

2. le gain maximal d'antenne permis (pour les dispositifs utilisant la bande 5725-5850 MHz) doit se conformer à la limite de p.i.r.e. spécifiée pour l'exploitation point à point et non point à point, selon le cas.